

Product Alert May 24, 2013

Type of Notification: Performance Related Concern

FM Approvals has been made aware of the potential of a performance issue with a diesel engine pump driver of the following description:

**Company Identity:** Cummins

Name: Cummins Fire Power

**Address:** 875 Lawrence Drive, De Pere, WI 54115 **Contact information:** Bob Janquart, Product Support Manager

920-338-5917

www.cumminsfirepower.com

**Product Identity:** Model CFP9E

**Description:** Diesel engine fire pump driver **Serial Number Ranges:** 46984170 through 46999201

73000277 through 73418774

**FM Approval status:** Currently FM Approved

**Hazard involved:** During routine testing of a CFP9E engine, the test model failed to recover to its rated speed. The problem was traced to a pressure relief valve in the fuel rail. There have been no field issues reported to Cummins or FM Approvals, however, Cummins will make appropriate replacement parts available for any location that has a CFP9E driver currently installed.

The Field Campaign Notice released by Cummins Fire Power can be found by following the hyperlink below:

http://www.cumminsfirepower.com/news/18apr13.htm

Thomas G. McCarty FM Approvals, Quality Department Norwood, MA, USA +1 (1)781 255 4802

Email: Thomas.mccarty@fmapprovals.com