



Product Alert

January 14th, 2019

Type of Notification: Misrepresentation of non-FM Approved Product

FM Approvals has been notified of the manufacture and sale of non-FM Approved New AsiaJoint Systems rigid grooved couplings incorrectly bearing the FM Approvals certification mark.

Company Identity: New AsiaJoint Systems Co. Ltd.

Address: 262, Neungseo-ro, Neungseo-myeon
Yeoju-si, Gyeonggido [Kyonggi-do]
Republic of Korea 469-812

Make/Model: AJ510

Product Identity: Grooved Couplings, Standard-Rigid

Description: Nominal pipe sizes (mm): 50, 65, 80, 100, 125, 150, 200

FM Approval Status: **Not FM Approved.**

Hazard Involved: The AJ510 rigid coupling has not been tested or examined by FM Approvals so the performance and reliability characteristics are unknown.

If you suspect you are in possession of any AJ510 rigid couplings bearing the FM Approvals certification marking, please bring that to the attention of:

Antonio L. Pires

FM Approvals, Quality Department

Norwood, MA, USA

+1 (1)781 255 4825

Email: Antonio.pires@fmapprovals.com

Figure 1 below shows an example of an AJ510 mislabeled with the FM Approvals marking. The FM marking is displayed on the side of the bolt pad on each housing of the coupling assembly. The model designation “AJ510” and the manufacturer designation “ASIA JOINT” are readily visible on each housing as well.



Figure 1. An example of the non-FM Approved model AJ510 rigid grooved coupling